# 3121 & 3123 W Almeria St., Phoenix, AZ 85009 List of Capital Improvements

# 3121 Unit 1

1.1. New 40 Gallon water heater

### 3121 Unit 4

- 2. Kitchen
  - 2.1. New Kitchen faucet
  - 2.2. Replaced kitchen sink drain system, strainer, and plumbing
  - 2.3. New range hood
  - 2.4. New kitchen ceiling light fixtures
  - 2.5. Replaced vent for gas stove going through the roof
  - 2.6. Refurbished gas stove
  - 2.7. Refurbished refrigerator
- 3. Bathroom
  - 3.1. New Vanity light fixture and vanity sink stopper
  - 3.2. Replaced medicine cabinet
  - 3.3. Bath hardware set 4 pieces
  - 3.4. Tub drain stopper
  - 3.5. Resurfaced tub, counters and sink
- 4. Interior
  - 4.1. New interior two-tone paint: Light gray & white
  - 4.2. Faux wood blinds
  - 4.3. New vinyl plank flooring
  - 4.4. Deadbolt combo kit for security door and entry door
  - 4.5. Ceiling fans
  - 4.6. Installed new smoke alarms

- 4.7. Bi-fold closet doors
- 4.8. New water heater

### 3123 Unit 1

- 1. Kitchen
  - 1.1. New Kitchen faucet
  - 1.2. Refurbished refrigerator
  - 1.3. Exhaust fan for kitchen range hood
  - 1.4. New vent for gas stove
  - 1.5. Cabinet Painting
- 2. Bathroom
  - 2.1. New toilet paper holder and drain stoppers
- 3. Installed new ceiling fans
  - 3.1. White, bedroom and dining room
- 4. Interior
  - 4.1. New vinyl flooring
  - 4.2. New interior two-tone paint: Light gray & white
  - 4.3. Faux wood blinds
  - 4.4. Deadbolt combo kit for security door and entry door
  - 4.5. Installed new smoke alarms
- 5. Exterior
  - 5.1. New 2.5 ton AC

# 3123 Unit 2

- 1. Kitchen
  - 1.1. Kitchen faucet
  - 1.2. Replaced vent for gas stove going through the roof
- 2. Bathroom

- 2.1. New vanity light fixture
- 2.2. Bath hardware set 4 pieces
- 2.3. Drain stoppers
- 2.4. Resurfaced tub, counters and sink
- 3. Interior
  - 3.1. New interior two-tone paint: Light gray & white
  - 3.2. Faux wood blinds
  - 3.3. Deadbolt combo kit for security door and entry door
  - 3.4. Installed new smoke alarms
  - 3.5. New Thermostat

# 3123 Unit 3

- 1. Bathroom
  - 1.1. Replaced bathroom sink cold water valve
  - 1.2. Replaced sink strainer.
  - 1.3. Resurfaced tub and sink
- 2. Interior
  - 2.1. Faux wood blinds
  - 2.2. New interior two-tone paint: Light gray & white
- 3. Kitchen
  - 3.1. Stove
  - 3.2. Hot water tank

#### 3123 Unit 4

- 4. Interior
  - 4.1. New interior two-tone paint: Light gray & white

# **All Units/Exterior**

# 1. New Plumbing

1.1. All sewer lines were replaced using a pipeless trenching technique.

- 1.1.1. Access holes were made in each bathroom, as well as outside of the building in order to pull through new pipes.
- 1.1.2. New HDPE pipe was pulled through the slab to all access locations.
- 1.1.3. Digging locations were backfilled while tempering. No landscaping was disturbed.

### 2. Other

- 2.1. Full Treatment Termidor HE: Full treatment with a 1-year warranty is transferable and renewable
- 2.2. New Exterior paint two tones, including doors and fascia
- 2.3. New Exterior Porch Lights (6 units)
- 2.4. New AC Filters all units

Joy S Pollard

3/2/2023

Docusigned by:

Joseph Baker

C193249F26D149B...

3/2/2023

3123 W Almeria, LLC